DETAILS OF FIRMWARE REV. 20190429 changes

The CG-6 Autograv™ firmware version 20190429 has the following additions and changes:

- Fixed intermittent issue where meter would not show up as USB device
- Synchronize the ADS1259 on each 1PPS event, so that there will be no periodic sampling glitch
- Manually reset GPS module by pressing UP and Down buttons under GPS menu (hardware update is needed for this feature)